



Worldwide repairs carried out with PolymerMetall®

REP-#141



A damaged injection mould for manufacturing plastic cups was repaired with MM-metal SS-steel.

MultiMetall
the MetalExistenceCompany®